UI Bulletin #106c

Subject: **Fuel Cap Tether Strap**

Models: Chevrolet Express/GMC Savana Cutaways with a service body installed

Model Years: 2012 and beyond

Date: December 13, 2012

Revision Date: June 6, 2014

ADVISORY:

This UI Bulletin is being created using information contained in General Motors Technical Bulletin PI0837

This bulletin was updated to include model years beyond 2012

Condition/Concern:

A condition may be caused by the fuel cap tether binding when installing the fuel cap and not allowing the fuel cap to seal completely or by the fuel cap tether being trapped between the fuel cap seal and the fuel fill pipe, not allowing the fuel cap to seal completely, possibly resulting in a Service Engine Soon Light being illuminated.

Repair/Recommendation:

To avoid the above noted condition, all vehicles with a service body installed and using a stainless steel tethered fuel cap (9B4) should tether the cap as shown below.



This

verses



Not This

General Motors Upfitter Integration

http://www.gmupfitter.com • 1-800-875-4742 (Upfitter Hotline)

Disclaimer: GM Upfitter Integration Technical Bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service and/or modification of a vehicle. These properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. Contact GM Upfitter Integration for information on whether the information is applicable your vehicle.